



Put the LCD in the shell




Paste the touchpad



Put the LCD in the shell

Soldering the audio L to S01
Soldering the audio R to S02



Connect the ribbon cable to Driverboard



Connect the LCD ribbon cable

CONNECT THE LED FIBER CABLE



Done!

